Document Log Item

Addressing			
From		То	
"Steven Costa" <glatzeldacosta@suddenlink.net></glatzeldacosta@suddenlink.net>		Carl Goldstein/R9/USEPA/US@EPA	
		"Matt Vojik" <vojik.matt@gmail.com></vojik.matt@gmail.com>	
сс		BCC	
"Joe Carney" <joe.carney@delmonte.com></joe.carney@delmonte.com>			
"Tim Ruby" <tim.ruby@delmonte.com></tim.ruby@delmonte.com>			
"Jim Cox" <jcox@cosintl.com></jcox@cosintl.com>			
"Samual Augspurger" <saugspurger@sampac.com></saugspurger@sampac.com>			
"Karen Glatzel" <kargatgdc@sı< td=""><td>uddenlink.net></td><td></td><td></td></kargatgdc@sı<>	uddenlink.net>		
Description			Form Used: Memo
Subject		Date/Time	
Prposed changes to teh Cannery Outfall		08/07/2008 05:35 PM	
# of Attachments	Total Bytes	NPM	Contributor
2	240,225		Marcela VonVacano
Processing			
Comments			

Body

Document Body

Carl, Matt;

Attached are two files: a transmittal letter and a Technical Memorandum as an attachment to the letter. You will be getting hard copies of these in a package of Cannery and ASPA monitoring reports that are going in the mail in a day or so. However, we wanted to make sure this did not get lost in the pile.

The canneries asked that we evaluate the possibility of opening more ports on the diffuser to reduce head loss under high flows. The attachment addresses this planned action and documents that there are no adverse effects, either environmentally or operationally.

Unless USEPA or ASEPA have concerns or objections, the canneries will plan on opening the two blocked ports later this year when they do an outfall inspection and routine maintenance.

Please give us a call or respond by email if you have questions or concerns. Thanks for your attention to this matter,

Regards

Steve Costa Karen Glatzel

216 Driftwood Lane PO Box 1238 Trinidad, CA 95570-1238 707-677-0123 (CA) 510-508-5020 (cell)

slcatgdc@earthlink.net

glatzeldacost@suddenlink.net - gdc Transmittal JCO Diffuser Modification.pdf - JCO Diffuser Performance - Final 080806.pdf